

TSB41BA3/A Errata

1 S100B Failed Connection Issue

1.1 Description

An S100B port of a TSB41BA3/A sometimes fails to make an active connection to an S100B port of another TSB41BA3/A after power up. The other ports on the TSB41BA3/A devices have active, functioning connections. The failed connection can occur across a CAT5 cable with TSB17BA1s and magnetics installed or it can occur on direct connections between two TSB41BA3/A devices.

Reading the registers of the TSB41BA3/As on either side of the failed connection reveals that both devices mark the failed connection with Loop_disable set in the page-0 port status register at Dh. A loop is not present in the system. A bus reset or series of bus resets does not re-enable the connection. A hard reset of one or both TSB41BA3/A devices may re-enable the connection in some cases.

It should be noted that once an active connection is made between two TSB41BA3/A devices, the connection is never dropped during normal operation or after a bus reset or even a hard reset due to this issue.

1.2 Cause

The S100B port transmit clock circuitry is not properly reset at power up, occasionally allowing the clock to initialize into an invalid state, thereby generating an incorrect frequency for S100B connections.

1.3 Workarounds

This issue will be fixed in an upcoming release of the TSB41BA3/A device: the TSB41BA3B. In the interim, there are some workaround possibilities:

1.3.1 Software Workaround

1. Set the TSB41BA3A mode so that all S100B connections are now set as S400B. For example, a mode-4 device would become a mode-6 device and a mode-12 device would become a mode-14 device. For this workaround, the mode change is permanent.
2. At power up, use the CSEL bit, which is located in the page-7 register, to force both PLLs on. This step must occur before any port connections are made, within ~600 ms of power up.
3. Set Max_Port_Speed to S100B for CAT5 ports. This step must be repeated after every hard reset.
4. As long as the preceding step is performed before the port connection is made (within ~600 ms of power up), no disabling/re-enabling of the ports is necessary.

1.3.2 Software/Hardware Workaround

1. Set the TSB41BA3A mode so that all S100B connections are set as S400B. For example, a mode-4 device would become a mode-6 device and a mode-12 device would become a mode-14 device.
2. At power up, use the CSEL bit, which is located in the page-7 register, to force both PLLs on. This step must occur before any port connections are made (within ~600 ms of power up).
3. Set the TSB41BA3A mode back to S100B.
4. Generate a hard reset via $\overline{\text{RESET}}$.

1.3.3 Hardware Workaround

This workaround is for active S100B ports only. It does not work for ports connected after power up.

1. Set the TSB41BA3A mode so that all S100B connections are now set as S400B. For example, a mode-4 device would become a mode-6 device, and a mode-12 device would become a mode-14 device.
2. Wait ~1 second to allow the active connections to fail (speed negotiation and training must complete). This requires both sides of the CAT5 connection to be configured to S400B to force the system to attempt to transmit at S400B.
3. Set the TSB41BA3A mode back to S100B in hardware.
4. Generate a hard reset via $\overline{\text{RESET}}$.

2 Disappearing IDLE in a Beta system Issue

2.1 Description

Disappearing IDLE in a Beta system results in max arbitration state timeout and bus reset. Specifically in Beta systems with more than four cable hops, unwanted bus resets may occur.

2.2 Cause

A short IDLE between a data packet and an arbitration grant disappears.

As signals propagate across the 1394 network, the IDLE between a data packet and an arbitration grant shortens since the time needed to repeat a data packet is longer than the time needed to repeat a grant.

2.3 Workaround

Add a 1394A PHY to the system to force legacy gap timing on the 1394 bus.

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

Products		Applications	
Amplifiers	amplifier.ti.com	Audio	www.ti.com/audio
Data Converters	dataconverter.ti.com	Automotive	www.ti.com/automotive
DSP	dsp.ti.com	Broadband	www.ti.com/broadband
Interface	interface.ti.com	Digital Control	www.ti.com/digitalcontrol
Logic	logic.ti.com	Military	www.ti.com/military
Power Mgmt	power.ti.com	Optical Networking	www.ti.com/opticalnetwork
Microcontrollers	microcontroller.ti.com	Security	www.ti.com/security
		Telephony	www.ti.com/telephony
		Video & Imaging	www.ti.com/video
		Wireless	www.ti.com/wireless

Mailing Address: Texas Instruments
Post Office Box 655303 Dallas, Texas 75265