# Trace properties
## TI Precision Labs – PSpice® for TI

Trace properties

- Right-click on a trace and select "Trace Property"

- Change properties of multiple traces:
  - Select traces with "Ctrl" (or "Shift")
    - Left click the trace you want to edit, right click to open the menu, select "Trace Property"

TEXAS INSTRUMENTS

Trace properties

- Customize settings to produce graphs
- Pick preferred color, pattern, width, symbol and select "OK"
- Graph will update with new changes

Results

- Figure 1 shows the traces PSpice automatically generates

- Figure 2 represents all customizations used from "Trace Properties"

Figure 1: Before Trace Properties

Figure 2: After Trace Properties

TEXAS INSTRUMENTS

Thanks for your time!

TEXAS INSTRUMENTS

To find more **PSpice® for TI** technical resources and search products, visit **ti.com/tool/PSPICE-FOR-TI**.

TEXAS INSTRUMENTS