# Cursors

TI Precision Labs – PSpice® for TI

Cursors

- Used to display exact coordinates of a point on a trace

- Also can be used to show two points on the same trace or one point on two different traces

- Can find the difference between points on your trace
  - Amplitude
  - Max and Min

TEXAS INSTRUMENTS

Turn cursors on and off

- To add cursors and turn on from navigation select Trace > Cursor > Display
 - Can also turn on from taskbar

Moving cursors left and right

- Cursors can be moved using left and right arrow keys

- Left-cursor can also be moved by left-clicking a specific point on the graph

- Right-click cursor can also be moved by right-clicking a specific point on the graph

- Navigate to Trace > Cursor to choose predefined cursor locations

Differences between cursors

- Cursor window displays trace name, trace color, and different Y-values
- Also displays the difference in Y-values between the 2 cursors

Change cursor properties

- Navigate to Tools > Options > Cursor Settings
- Here you can change color and width of cursors

Place label on graph

- Move cursor to desired location of label
- Navigate to Plot > Label > Mark
  - Can also use taskbar

Changing label features

- Label text and location can be changed by double-clicking the label
  - Label font, font style, size, and color can be changed by selecting "Change Font" from the popup window

Thanks for your time!

TEXAS INSTRUMENTS

To find more **PSpice® for TI** technical resources and search products, visit **ti.com/tool/PSPICE-FOR-TI**.

TEXAS INSTRUMENTS