Contents of MSP430F471x6, MSP430F471x7 Code Examples (slac282.zip) -.s43 (IAR) and .c (CCS & IAR)

Link to zip file: http://www.ti.com/lit/zip/slac282

Applicable Devices: MSP430F47166, MSP430F47176, MSP430F47186, MSP430F47196, MSP430F47167, MSP430F47177,

MSP430F47187, MSP430F47197

Consult readme.txt included in the zip file for disclaimer and coding style guidelines

Contents:

- Assembly Code Examples (.s43. IAR compatible)
- <u>C Code Examples (.c, IAR & CCS compatible)</u>

.s43 code examples – IAR		
File name	Description	
msp430x471x7_1.s43	Software Toggle P5.1	
msp430x471x7_bt_01.s43	Basic Timer, Toggle P5.1 Inside ISR, 32kHz ACLK	
msp430x471x7_bt_02.s43	Basic Timer, Toggle P5.1 Inside ISR, DCO SMCLK	
msp430x471x7_clks_02.s43	FLL+, Output 32kHz Xtal + HF Xtal + Internal DCO	
msp430x471x7_compA_01.s43	Comparator A, Poll input CAO, result in P5.1	
msp430x471x7_compA_02.s43	Comparator A, Poll input CAO, CA exchange, result in P5.1	
msp430x471x7_compA_04.s43	Comparator A, Poll input CAO, result in P5.1	
msp430x471x7_compA_05.s43	Comparator A, Poll input CAO, interrupt triggered	
msp430x471x7_flashwrite_01.s43	Flash In-System Programming, Copy SegC to SegD	
msp430x471x7_flashwrite_03.s43	Flash In-System Programming w/ EEI, Copy SegC to SegD	
msp430x471x7_flashwrite_04.s43	Flash In-System Programming w/ EEI, Copy SegD to A/B/C	
msp430x471x7_fll_01.s43	FLL+, Runs Internal DCO at 2.45MHz	
msp430x471x7_fll_02.s43	FLL+, Runs Internal DCO at 16MHz	
msp430x471x7_hfxt2.s43	FLL+, MCLK Configured to Operate from XT2 HF XTAL	
msp430x471x7_lcda_04.s43	LCD_A Put "0123456" on SBLCDA4 LCD	
msp430x471x7_lcda_05.s43	LCD_A Put "0123456" on SBLCDA4 LCD with charge pump	
msp430x471x7_lpm3.s43	FLL+, LPM3 Using Basic Timer ISR, 32kHz ACLK	
msp430x471x7_MPY_01.s43	16x16 Unsigned Multiply	
msp430x471x7_MPY_03.s43	16x16 Signed Multiply	
msp430x471x7_MPY_09.s43	32x32 Unsigned Multiply	
msp430x471x7_MPY_10.s43	32x32 Signed Multiply	
msp430x471x7_MPY_11.s43	32x32 Signed Multiply Accumalate	
msp430x471x7_MPY_12.s43	32x32 Unsigned Multiply Accumalate	
msp430x471x7_MPY_13.s43	Saturation mode overflow test	
msp430x471x7_MPY_14.s43	Saturation mode underflow test	
msp430x471x7_MPY_15.s43	Fractional mode, Q15 multiplication	
msp430x471x7_OF_LFXT1_nmi.s43	LFXT1 Oscillator Fault Detection	
msp430x471x7_OF_XT2.s43	XT2 Oscillator Fault Detection	
msp430x471x7_P1_01.s43	Software Poll P2.7, Set P5.1 if P2.7 = 1	
msp430x471x7_P1_02.s43	Software Port Interrupt on P2.7 from LPM4	
msp430x471x7_P1_05.s43	Write a byte to Port 1	
msp430x471x7_P7_05.s43	Write a byte to Port 7	

msp430x471x7_P8_05.s43	Write a byte to Port 8
msp430x471x7_PA_05.s43	Write a Word to Port A (Port7+Port8)
msp430x471x7_PB_05.s43	Write a Word to Port B (Port9+Port10)
msp430x471x7_rtc_01.s43	Real Time Clock, Toggle P5.1 Inside ISR, 32kHz ACLK
msp430x471x7_rtc_02.s43	Real Time Clock, Toggle P5.1 Inside ISR, 32kHz ACLK and send Time via UART
msp430x471x7_sd16_01.s43	SD16, Continuous Conversion on a Group of 7 Channels
msp430x471x7_sd16_02.s43	SD16, Single Conversion on a Group of 7 Channels
msp430x471x7_sd16_03.s43	SD16, Continuous Conversion on a Single Channel
msp430x471x7_sd16_04.s43	SD16, Single Conversion on Single Channel Polling IFG
msp430x471x7_sd16_05.s43	SD16, Single Conversion on a Single Channel Using ISR
msp430x471x7_svs_01.s43	SVS, POR @ 2.5V Vcc
msp430x471x7_svs_03.s43	SVS, Toggle port 5.1 on Vcc < 2.8V
msp430x471x7_ta_01.s43	Timer_A, Toggle P5.1, CCR0 Cont. Mode ISR, DCO SMCLK
msp430x471x7_ta_02.s43	Timer_A, Toggle P5.1, CCR0 Up Mode ISR, DCO SMCLK
msp430x471x7_ta_03.s43	Timer_A, Toggle P5.1, Overflow ISR, DCO SMCLK
msp430x471x7_ta_04.s43	Timer_A, Toggle P5.1, Overflow ISR, 32kHz ACLK
msp430x471x7_ta_05.s43	Timer_A, Toggle P5.1, CCR0 Up Mode ISR, 32kHz ACLK
msp430x471x7_ta_16.s43	Timer_A, PWM TA1-2 Up Mode, DCO SMCLK
msp430x471x7_ta_17.s43	Timer_A, PWM TA1-2 Up Mode, 32kHz ACLK
msp430x471x7_tb_01.s43	Timer_B, Toggle P5.1, CCR0 Cont. Mode ISR, DCO SMCLK
msp430x471x7_tb_02.s43	Timer_B, Toggle P5.1, CCR0 Up Mode ISR, DCO SMCLK
msp430x471x7_tb_03.s43	Timer_B, Toggle P5.1, Overflow ISR, DCO SMCLK
msp430x471x7_tb_04.s43	Timer_B, Toggle P5.1, Overflow ISR, 32kHz ACLK
msp430x471x7_tb_05.s43	Timer_B, Toggle P5.1, CCR0 Up Mode ISR, 32kHz ACLK
msp430x471x7_tb_10.s43	Timer_B, PWM TB1-2 Up Mode, DCO SMCLK
msp430x471x7_tb_11.s43	Timer_B, PWM TB1-2 Up Mode, 32kHz ACLK
msp430x471x7_uscia0_duplex_9600.s43	USCI_A0, UART 9600 Full-Duplex Transceiver, 32K ACLK
msp430x471x7_uscia0_irda_01.s43	USCI_A0 IrDA External Loopback Test, 4MHz SMCLK
msp430x471x7_uscia0_spi_09.s43	USCI_A0, SPI 3-Wire Master Incremented Data
msp430x471x7_uscia0_spi_10.s43	USCI_A0, SPI 3-Wire Slave Data Echo
msp430x471x7_uscia0_uart_115k.s43	USCI_A0, 115200 UART Echo ISR, DCO SMCLK
msp430x471x7_uscia0_uart_115k_lpm.s43	USCI_A0, 115200 UART Echo ISR, DCO SMCLK, LPM3
msp430x471x7_uscia0_uart_9600.s43	USCI_A0, Ultra-Low Pwr UART 9600 Echo ISR, 32kHz ACLK
msp430x471x7_uscib0_i2c_08.s43	USCI_B0 I2C Master TX multiple bytes to MSP430 Slave
msp430x471x7_uscib0_i2c_09.s43	USCI_B0 I2C Slave RX multiple bytes from MSP430 Master
msp430x471x7_uscib0_i2c_10.s43	USCI_B0 I2C Master RX multiple bytes from MSP430 Slave
msp430x471x7_uscib0_i2c_11.s43	USCI_B0 I2C Slave TX multiple bytes to MSP430 Master
msp430x471x7_uscib0_spi_01.s43	USCI_B0, SPI Interface to TLC549 8-Bit ADC
msp430x471x7_wdt_01.s43	WDT, Toggle P5.1, Interval Overflow ISR, DCO SMCLK
msp430x471x7_wdt_02.s43	WDT, Toggle P5.1, Interval Overflow ISR, 32kHz ACLK
msp430x471x7_wdt_04.s43	WDT+ Failsafe Clock, DCO SMCLK
msp430x471x7_wdt_05.s43	Reset on Invalid Address fetch, Toggle P5.1
msp430x471x7_wdt_06.s43	WDT+ Failsafe Clock, 32kHz ACLK

C code examples – IAR & CCS		
File name	Description	
msp430x471x7_1.c	Software Toggle P5.1	
msp430x471x7_bt_01.c	Basic Timer, Toggle P5.1 Inside ISR, 32kHz ACLK	
msp430x471x7_bt_02.c	Basic Timer, Toggle P5.1 Inside ISR, DCO SMCLK	
msp430x471x7_clks_02.c	FLL+, Output 32kHz Xtal + HF Xtal + Internal DCO	
msp430x471x7_compA_01.c	Comparator A, Poll input CAO, result in P5.1	
msp430x471x7_compA_02.c	Comparator A, Poll input CAO, CA exchange, result in P5.1	
msp430x471x7_compA_04.c	Comparator A, Poll input CAO, result in P5.1	
msp430x471x7_compA_05.c	Comparator A, Poll input CAO, interrupt triggered	
msp430x471x7_dma_01_IAR.c	DMAO, Repeated Burst to-from RAM, Software Trigger	
msp430x471x7_dma_02_IAR.c	DMAO, Repeated Block to P5OUT, TACCR2 Trigger	
msp430x471x7_dma_03_IAR.c	DMA0, Repeated Block UCA1UART 9600, TACCR2, ACLK	
msp430x471x7_dma_04_IAR.c	DMA0, Block Mode UARTO 9600, ACLK	
msp430x471x7_flashwrite_01.c	Flash In-System Programming, Copy SegC to SegD	
msp430x471x7_flashwrite_03.c	Flash In-System Programming w/ EEI, Copy SegC to SegD	
msp430x471x7_flashwrite_04.c	Flash In-System Programming w/ EEI, Copy SegD to A/B/C	
msp430x471x7_fll_01.c	FLL+, Runs Internal DCO at 2.45MHz	
msp430x471x7 fll 02.c	FLL+, Runs Internal DCO at 16MHz	
msp430x471x7_hfxt2.c	FLL+, MCLK Configured to Operate from XT2 HF XTAL	
msp430x471x7_lcda_04.c	LCD_A Put "0123456" on SBLCDA4 LCD	
msp430x471x7_lcda_05.c	LCD_A Put "0123456" on SBLCDA4 LCD with charge pump	
msp430x471x7_lpm3.c	FLL+, LPM3 Using Basic Timer ISR, 32kHz ACLK	
msp430x471x7_MPY_01.c	16x16 Unsigned Multiply	
msp430x471x7 MPY 03.c	16x16 Signed Multiply	
msp430x471x7_MPY_09.c	32x32 Unsigned Multiply	
msp430x471x7_MPY_10.c	32x32 Signed Multiply	
msp430x471x7_MPY_11.c	32x32 Signed Multiply Accumalate	
msp430x471x7_MPY_12.c	32x32 Unsigned Multiply Accumalate	
msp430x471x7_MPY_13.c	Saturation mode overflow test	
msp430x471x7 MPY 14.c	Saturation mode underflow test	
msp430x471x7_MPY_15.c	Fractional mode, Q15 multiplication	
msp430x471x7 OF LFXT1 nmi.c	LFXT1 Oscillator Fault Detection	
msp430x471x7 OF XT2.c	XT2 Oscillator Fault Detection	
msp430x471x7_P1_01.c	Software Poll P2.7, Set P5.1 if P2.7 = 1	
msp430x471x7_P1_02.c	Software Port Interrupt on P2.7 from LPM4	
msp430x471x7 P1 05.c	Write a byte to Port 1	
msp430x471x7 P7 05.c	Write a byte to Port 7	
msp430x471x7_P8_05.c	Write a byte to Port 8	
msp430x471x7_PA_05.c	Write a Word to Port A (Port7+Port8)	
msp430x471x7 PB 05.c	Write a Word to Port B (Port9+Port10)	
msp430x471x7_rtc_01.c	Real Time Clock, Toggle P5.1 Inside ISR, 32kHz ACLK	
msp430x471x7 rtc 02.c	Real Time Clock, Toggle P5.1 Inside ISR, 32kHz ACLK and send Time via UART	
msp430x471x7_sd16_01.c	SD16, Continuous Conversion on a Group of 7 Channels	

	-
msp430x471x7_sd16_02.c	SD16, Single Conversion on a Group of 7 Channels
msp430x471x7_sd16_03.c	SD16, Continuous Conversion on a Single Channel
msp430x471x7_sd16_04.c	SD16, Single Conversion on Single Channel Polling IFG
msp430x471x7_sd16_05.c	SD16, Single Conversion on a Single Channel Using ISR
msp430x471x7_sd16_06.c	SD16, Using the Integrated Temperature Sensor
msp430x471x7_svs_01.c	SVS, POR @ 2.5V Vcc
msp430x471x7_svs_03.c	SVS, Toggle port 5.1 on Vcc < 2.8V
msp430x471x7_ta_01.c	Timer_A, Toggle P5.1, CCR0 Cont. Mode ISR, DCO SMCLK
msp430x471x7_ta_02.c	Timer_A, Toggle P5.1, CCR0 Up Mode ISR, DCO SMCLK
msp430x471x7_ta_03.c	Timer_A, Toggle P5.1, Overflow ISR, DCO SMCLK
msp430x471x7_ta_04.c	Timer_A, Toggle P5.1, Overflow ISR, 32kHz ACLK
msp430x471x7_ta_05.c	Timer_A, Toggle P5.1, CCR0 Up Mode ISR, 32kHz ACLK
msp430x471x7_ta_16.c	Timer_A, PWM TA1-2 Up Mode, DCO SMCLK
msp430x471x7_ta_17.c	Timer_A, PWM TA1-2 Up Mode, 32kHz ACLK
msp430x471x7_tb_01.c	Timer_B, Toggle P5.1, CCR0 Cont. Mode ISR, DCO SMCLK
msp430x471x7_tb_02.c	Timer_B, Toggle P5.1, CCR0 Up Mode ISR, DCO SMCLK
msp430x471x7_tb_03.c	Timer_B, Toggle P5.1, Overflow ISR, DCO SMCLK
msp430x471x7_tb_04.c	Timer_B, Toggle P5.1, Overflow ISR, 32kHz ACLK
msp430x471x7_tb_05.c	Timer_B, Toggle P5.1, CCR0 Up Mode ISR, 32kHz ACLK
msp430x471x7_tb_10.c	Timer_B, PWM TB1-2 Up Mode, DCO SMCLK
msp430x471x7_tb_11.c	Timer_B, PWM TB1-2 Up Mode, 32kHz ACLK
msp430x471x7_uscia0_duplex_9600.c	USCI_A0, UART 9600 Full-Duplex Transceiver, 32K ACLK
msp430x471x7_uscia0_irda_01.c	USCI_A0 IrDA External Loopback Test, 4MHz SMCLK
msp430x471x7_uscia0_spi_09.c	USCI_A0, SPI 3-Wire Master Incremented Data
msp430x471x7_uscia0_spi_10.c	USCI_A0, SPI 3-Wire Slave Data Echo
msp430x471x7_uscia0_uart_115k.c	USCI_A0, 115200 UART Echo ISR, DCO SMCLK
msp430x471x7_uscia0_uart_115k_lpm.c	USCI_A0, 115200 UART Echo ISR, DCO SMCLK, LPM3
msp430x471x7_uscia0_uart_9600.c	USCI_A0, Ultra-Low Pwr UART 9600 Echo ISR, 32kHz ACLK
msp430x471x7_uscib0_i2c_08.c	USCI_B0 I2C Master TX multiple bytes to MSP430 Slave
msp430x471x7_uscib0_i2c_09.c	USCI_B0 I2C Slave RX multiple bytes from MSP430 Master
msp430x471x7_uscib0_i2c_10.c	USCI_B0 I2C Master RX multiple bytes from MSP430 Slave
msp430x471x7_uscib0_i2c_11.c	USCI_B0 I2C Slave TX multiple bytes to MSP430 Master
msp430x471x7_uscib0_spi_01.c	USCI_B0, SPI Interface to TLC549 8-Bit ADC
msp430x471x7_wdt_01.c	WDT, Toggle P5.1, Interval Overflow ISR, DCO SMCLK
msp430x471x7_wdt_02.c	WDT, Toggle P5.1, Interval Overflow ISR, 32kHz ACLK
msp430x471x7_wdt_04.c	WDT+ Failsafe Clock, DCO SMCLK
msp430x471x7_wdt_05.c	Reset on Invalid Address fetch, Toggle P5.1
msp430x471x7_wdt_06.c	WDT+ Failsafe Clock, 32kHz ACLK

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of TI information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation. Information of third parties may be subject to additional restrictions

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

TI products are not authorized for use in safety-critical applications (such as life support) where a failure of the TI product would reasonably be expected to cause severe personal injury or death, unless officers of the parties have executed an agreement specifically governing such use. Buyers represent that they have all necessary expertise in the safety and regulatory ramifications of their applications, and acknowledge and agree that they are solely responsible for all legal, regulatory and safety-related requirements concerning their products and any use of TI products in such safety-critical applications, notwithstanding any applications-related information or support that may be provided by TI. Further, Buyers must fully indemnify TI and its representatives against any damages arising out of the use of TI products in such safety-critical applications.

TI products are neither designed nor intended for use in military/aerospace applications or environments unless the TI products are specifically designated by TI as military-grade or "enhanced plastic." Only products designated by TI as military-grade meet military specifications. Buyers acknowledge and agree that any such use of TI products which TI has not designated as military-grade is solely at the Buyer's risk, and that they are solely responsible for compliance with all legal and regulatory requirements in connection with such use.

TI products are neither designed nor intended for use in automotive applications or environments unless the specific TI products are designated by TI as compliant with ISO/TS 16949 requirements. Buyers acknowledge and agree that, if they use any non-designated products in automotive applications, TI will not be responsible for any failure to meet such requirements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

Applications Products Amplifiers amplifier.ti.com Audio www.ti.com/audio Data Converters Automotive www.ti.com/automotive dataconverter.ti.com DLP® Products Broadband www.dlp.com www.ti.com/broadband DSP Digital Control dsp.ti.com www.ti.com/digitalcontrol Clocks and Timers www.ti.com/clocks Medical www.ti.com/medical Military Interface www.ti.com/military interface.ti.com Optical Networking Logic logic.ti.com www.ti.com/opticalnetwork Power Mgmt power.ti.com Security www.ti.com/security Telephony Microcontrollers microcontroller.ti.com www.ti.com/telephony Video & Imaging www.ti-rfid.com www.ti.com/video RF/IF and ZigBee® Solutions www.ti.com/lprf Wireless www.ti.com/wireless

> Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265 Copyright © 2009, Texas Instruments Incorporated